

## HEAD PULLEY RELOCATION

---



---

Client: Highland Valley Copper

Description: The stacker feed conveyor's head pulley was moved to accommodate increased belt speed as required for capacity improvement.